Technical Service Bulletin

2718

Subject:

ABS/ESP Telltale Illuminates - Several Trouble Codes are set

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:	
		from	to	from	1	to		
Opel,Vauxhall	Astra-J	2010	2011	AG000001		BG065859	All	All
Opel,Vauxhall	Astra-J	2010	2011	A8000001		B8051130	All	All
Opel,Vauxhall	Astra-J	2010	2011	A3000001		B3006861	All	All
Opel,Vauxhall	Insignia	2009	2011	91000001		B1087208	All	All

Option

Chassis Continuously Variable Real Time Damping (RPO F45 & GNA).

Complaint

ABS/ESP telltale illuminates.

Cause

Continuously variable real time damping setting doesn't work. 1.) Broken cable inside the chassis continuously variable real time damping wiring harness 2.) Moisture in the wiring harness plug at the suspension strut

Production

As of the following VINs an improved wiring harness routing has been implemented: Insignia: W0LGT8EE0B1087208 (10-Dec-2010) Astra J: Gliwice: W0LPE6EN3BG065859 (11-Jan-2011) Ellesmere Port: W0LPC6ET4B8051130 (19-Jan-2011) St. Petersburg: XUFPE6EJ7B3006861 (14-Feb-2011)

Remedy

Attention:

Claims will only be accepted for vehicles built before the breakpoints listed under "Production"!

In case of customer complaint first check the continuously variable $% \left(\frac{1}{2}\right) =\left(\frac{1}{2}\right) \left(\frac{1}{2}$ real time damping wiring harness for broken cables.

If no broken cable can be found check the wiring harness plug contacts of the CDC sensor, the CDC valve and the ABS sensor at the suspension struts for corrosion and replace if required.

Important:

Pay attention to the NEW routing of the continuously variable real time damping wiring harness!

Note:

The following DTC may be set: Code: DTC C0035, DTC C0040, DTC C0575, DTC C0580, DTC C0670, DTC C0675

Working Procedure:


1. Check continuously variable real time damping wiring harness for broken cable (Picture I, arrow)

No external cracks will be visible.

- Measure wiring harness resistance while moving the harness back and forward in shown area (Picture I, arrow)


Note:

If a cable is broken inside the continuously variable real time damping wiring harnesses replace the wiring harness by the ${\tt NEW}$ improved version on both sides.



2. Replace continuously variable real time damping wiring harness (Picture II, 1)

If the replacement of the continuously variable real time damping wiring harness is required, pay attention to the NEW routing, as shown in picture II!



- 3. Check continuously variable real time damping wiring harness plug for corrosion (Picture I)
 - Continuously variable real time damping wiring harness plug (1)

 - Wiring harness plug CDC valve (2)
 Wiring harness plug CDC sensor (3)
 Wiring harness plug ABS sensor (4)

Note:

Replace corroded component on both sides.

Spare-Parts: Part-No.: Catalogue-No.:

Astra-J: Harness, Assy.	, Suspension Levelling	13356764	12 77 529
Insignia: Harness, Assy.	, Suspension Levelling	13356790	12 77 530
Labour Times:		TC:	Hours:
U3 271 80	CDC Wiring Harness Replacement	90	SA

The costs for this repair will be covered during warranty and policy. For policy please refer to the Policy Guideline (WebPG/Kuugel). The regular Warranty Procedure will apply.

FunctionalGroup	E - Front wheel suspension/Wheels/Tyres	
Complaint Group	04 - Electrical failures,06 - Failure Code Setting by Control Unit	
Trouble Code	C0035,C0040,C0575,C0580,C0670,C0675	

© 2010 ADAM OPEL AG. All Rights Reserved. The reproduction, distribution or modification is not permitted.