

Technical Service Bulletin

2621

Subject: **Display - Flickering**

Brand:	Model:	Model Year:	VIN:	Engine:	Transmission:
		from to	from to		
Opel, Vauxhall	Astra-J	2010 -	A?000001	All	All

Option**Complaint****Cause****Production**

Display flickering.
Display flickering due to interference from the cell phone to USB connector.

Remedy

In case of customer complaint, please advise the customer to store the cell phone NOT close to the USB connector.

Installation of below listed improved USB connectors improves the behaviour.

Spare-Parts:	Part-No.:	Catalogue-No.:
USB Connector (Jet Black)	13349323	17 80 525
USB Connector (Cocoa)	13349324	17 80 526

FunctionalGroup**Complaint Group****Trouble Code**

N - Electrical Equipment
04 - Electrical failures,13 - No/Poor Function
None

© 2010 ADAM OPEL AG. All Rights Reserved. The reproduction, distribution or modification is not permitted.