Technical Service Bulletin 2672

Subject: **Engine A20DTx Engine Management System - "Oil Pressure too low, shut off engine" appears in instrument cluster**

Brand:	Model:	Model Year: from	to	VIN: from	to	Engine:	Transmission:
Opel, Vauxhall	Insignia	2009	2010	91000362	A1134667	A20DTC| A20DTH| A20DTJ	All
Opel, Vauxhall	Astra-J	2010	2010	A?000001	A?129026	A20DTH	All

Option	
Complaint	Customer reports about "oil pressure too low, shut off engine" message shows up in instrument panel.
Cause	Software deviation in Engine Management System.
Production	Implementation of a revised calibration in MY2011.

Remedy

```
In case of customer complaint please program engine control unit with
the latest software available on TIS2Web.


Please note:
It is not necessary to replace any parts.


Note:
Applying this software update might lead to a slight jerking
condition in the 6th gear between 77 and 81 km/h as described
in TSB 2824.


Labour Times:                          TC:       Hours:


U3 267 20     Program ECM              90        0.3


The costs for this repair will be covered during warranty and policy.
For policy please refer to the Policy Guideline (WebPG/Kuugel).
The regular Warranty Procedure will apply.
```

FunctionalGroup	J - Engine
Complaint Group	23 - Wrong Indication
Trouble Code	

© 2010 ADAM OPEL AG. All Rights Reserved. The reproduction, distribution or modification is not permitted.