

Field Remedy: 2601

Subject: Engine A20DTx - Delayed engine speed decrease when shifting

Models:	Engines:	Option:
Astra-J 2010...,Insignia 2009...	A20DTH,A20DTC A20DTH A20DTJ	Only Manual Transmission

Complaint:	After SPS programming with latest update (e.g. Customer Satisfaction Program 09-R-040) the engine speed will not fall to idle when shifting down, but stay for a short time at ~2000 RPM.
Cause:	Software change to enable a smoother shifting operation.
Production:	This comfort function was introduced for Astra-J & Insignia A20DTx engines as of MY 2010 and is now also backwards compatible for MY 2009.

Remedy:

In case of customer complaint inform customer accordingly. Do not perform any further reprogramming or repair attempts.

FunctionalGroup:	J - Engine
Complaint Group:	18 - Poor Driveability
Trouble Code:	None

© 2010 ADAM OPEL AG. All Rights Reserved. The reproduction, distribution or modification is not permitted.